




▪
▪
▪
▪
▪
▪



Part No	Inductance (μ H)	Tolerance	Temperature Rise Current Typ. (A)	Satura on Current Typ. (A)	DC Resistance Typ. (m)	DC Resistance Max. (m)

°C

°C

°C

